
Troubleshooting_Extrusion





C

ontents

Preparation for Troubleshooting

5-Step Troubleshooting

Typical Troubles during Extrusion

Preparation for Troubleshooting

- Acquiring the process data
 - Measuring process variables : Be sure to check and record every data because it acts like a black box
 - Set temp. and current temp. of barrel (cylinder), and die
 - Resin temperature(°C)
 - Resin pressure(bar)
 - Motor torque(A, %)

- Acquire extrusion theories and case studies

- Analyze past processing data, and compare it with the current one
 - Compare the process variables in the past (which was in normal state) with the current one
 - ① Process information ← Measured process variables
 - ② Reliability of the measured data ← Checking whether various sensors and heaters are malfunctioning
 - ③ Information of the screw dimensions ← Checking whether it is worn out or not
 - ④ Information of the resin in use ← Check rheological, thermal, and mechanical properties

- Collaboration between production/quality/purchasing/equipment team members

5-Step Troubleshooting

▪ 1-Step : Understanding the problem

- List the possible causes, review the process conditions of a normal state, comparing with the past/ present phenomenon
 - ① Uneven supply of a raw material
 - ② Improper extruder temp. setting and melt temp. of a resin
 - ③ Improper drying or cooling
 - ④ Contaminants
 - ⑤ Improper puller (or haul-off) speed

▪ 2-Step : Resolving the problems

- Although it is not a permanent solution, immediate action is required to resolve the underlying problem.


▪ 3-Step : Identifying essential causes

- Basic inspection of process quality management 5M + 1E
 - ① Man : Whether or not the operator is working improperly
 - ② Machine : Whether the machine/structure is broken or not
 - ③ Measurement : Check process conditions, whether the physical properties of final product is measured properly
 - ④ Material : Check whether the content of stabilizers and additives are adequate, and blending procedure is OK
 - ⑤ Method : Whether the correct process conditions are fulfilled
 - ⑥ Environment : Check if there are inadequate working environment such as temperature/humidity/contaminant


5-Step Troubleshooting

- If needed, use brainstorming, fishbone diagrams, pareto analysis etc. to identify one or more hidden causes

Fishbone diagram : Reasons for voids



Pareto diagram : Reasons for voids




4-Step : Actions

- Providing optimal solutions through communication with customers
 - ① Minimize cost
 - ② Minimize time spending
 - ③ Guarantee reliability
- Improvement of product's color, physical properties, size, surface quality, etc.

5-Step : Final process monitoring

- After corrective action, final monitoring is required to ensure that the problem has been resolved properly and has not recurred.

Change/Variation of Extrusion Volume




- Keeping constant level of resin in the hopper
- Check the room temp. and humidity
- Check the voltage deviation in the factory



- Introduce real-time data measurement device
- Check alignment of screw, gearbox and motor
- Reduced shear stress of die land
 - Increase die setting temp.
 - Widen the die gap
 - Reduce extrusion volume

- Optimize screw design
 - Adjust screw compression ratio
 - Increase screw compression length
 - Introduce&use screw cooling system
- Check barrel/die temperature control



Pressure and Torque Fluctuations



Stable extrusion




Unstable extrusion




Surging

- Surging : A phenomenon which extrusion volume is not constant and shakes





Screw Wear-out


- Clearance increase due to screw wear out
 - Inevitable deformation of the screw → Contact with the barrel surface when rotating → Screw flight wear out
 - Reduces productivity (Fluctuate decrease or deviation) or reduces extrusion uniformity (increased temp. deviation)
- Screw should be regularly managed



Cross-section of screw



Deterioration/Carbonization



High Resin Temp. & High Motor Torque

▪ High resin temperature

- Screw design aspect
 - ① Relationship between channel depth and RPM : Viscous heat
 - ② Excessive or inadequate dispersion of mixing element (Maddock, Egan etc.)
- Processing aspect
 - ① Check barrel temp. control unit
 - ② Check barrel cooling unit
 - ③ Die pressure reduction



Standard Maddock screw : Local overheating is possible



Upgraded screw : Suppress local overheating

▪ High motor torque

- Check list
 - ① Whether the screw design is suitable for the resin
 - ② Whether the length of the extruder (screw) is appropriate to the resin
 - ③ Whether the current processing conditions are appropriate compared to the previous one
 - ④ Whether the barrel and die heaters are working properly
 - ⑤ Possibility of resin retention inside the extruder

Deformation of the Product

Random deformation

Differences in physical properties
of raw materials

Complex problem of
screw RPM, Pressure, and barrel temp. etc

Check raw material mechanical property (lot by lot)
ex) molecular weight, viscosity

- All process condition need to be monitored
- Collect torque pressure data


Deformation over time

External energy input changing according to the time


Change of molecular weight

- Check whether the melt temperature and pressure of the resin are constant
- Make sure the extruder's temperature control is working properly
- Check external environmental factors
ex) Inflow of cold air and temp. of pellet
- Check raw material's molecular weight by manufacturing date


Warpage



- Shrinkage and warpage with regard to cooling rate




Weld line




- Increase entanglement in molecules
: Increase barrel temp., pressure, or die temp.
- Increase die length to provide sufficient flow to increase intramolecular entanglement
- Change die design for resin to be mixed after polymer flow is recombined

- Weld line creation process inside the die




Die line




- Change mixing screw (ex. Maddock)
- Increase barrel temp increase mixing efficiency

- Problem of die fastening
- Scratch on the die flow path
- Resin stagnation inside or at the exit of the die
- Die design defect



Die line

Melt Fracture




- Method : Die & Screw metering section temp increase
- Characteristics : Internal die stress decrease
- Limits : Reduced resin shape retention, color change, carbonization

Change die structure

- Method : Increase die land
- Characteristics : Securing sufficient stress relief time inside the die
- Limits : Pressure increase, facility space constraints, new investment costs, etc.



- Method : Addition of lubricants such as PPA* or wax etc.
- Characteristics : Reduces stress by inducing slip on the die surface
- Limits : Affects physical properties, might not have expected effects etc.

*PPA : Polymer Processing Aid




<Image of Melt fracture according to Shear stress>


Bubbles




Gel



Microscope image by gel type




Typical spherical shape



Carbide




Contaminants (atypical dust, fibers)





Colored contaminant

Drool

- Die drool : Accumulation of material on the outer side of the die



- Die drool change according to sheet extrusion time



Thank you

감사합니다

